General Environmental Incident Summary

Incident: 3893 Date/Time Notice: 9/3/2015 1604 DEM Incident No:

Responsible Party: Oneok Rockies Midstream, LLC.

Date Incident: 8/27/2015 Time Incident: 0715 Duration: 1 minutes

County: McKenzie Twp: 150 Rng: 101 Sec: 36 Qtr: NE

Lat: 47.77228 Long: -103.54270 Method: Navigation quality GPS

Location Description: 130th Ave NW, one mine north of ND-200 US-85

Submitted By: Benjamin Rozell Affiliation: Site Energy EHS Advisor

Address: 315 Main Street #751

City: New Town State: ND Zip: 58763

Received By:

Contact Person: Nadia Kyrylova

2700 Lincoln Avenue SE Sidney, ND 59270

Distance Nearest Occupied Building: 600 Feet Release Contained: Yes

Type of Incident: Equipment break

Description of Released Contaminant: Rotella T SAE15w-40 Engine Oil

Volume Spilled: 0.10 gallons Ag Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident:

Bolts holding the power steering pump in place backed out causing motor oil to spill.

Risk Evaluation:

none

of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

none

Action Taken or Planned:

Mechanic laid down cardboard with absorbent towels on top of the cardboard to catch any remaining oil from contacting the ground. Vehicle was repaired and contaminated soil will be taken to a disposal site. Before the mechanic reinstalled the bolts he applied Loctite on the bolts to prevent future occurrences.

Wastes Disposal Location: Tervita Alexander, North Dakota

Agencies Involved:

Updates

Date: 9/3/2015 Status: Reviewed; No Followup Required Author: Crowdus, Kory

Updated Volume:

Notes:

Due to small amount released and rapid cleanup, no followup required.